# L-type ENGINE TUNING PARTS



#### KAMEARI Reinforced Head Stud Bolt L6 SET

By using stud bolts, the cylinder block threads can be fully used. This distributes the stress generated by tightening over the entire thread, reducing cylinder deformation by about half and improving accuracy. In addition, the use of large-diameter washers increase the contact area, allowing the tightening force to be transmitted over a wide area.



L6 SET ÿ35,000

detail

•Stud bolt •Kameari

Kameari Chromoly SCM435 Outer diameter 22 x Inner diameter 11 x Thickness 3.0 (Reference

uter diameter: ARP = 20) Nut ARP M10 x P1.25 lolybdenum grease ARP No. 100-9908 , wrench ize M12 12-Molybdenum grease

used)•Tightening sided 8.3kgf•m (ARP grease torque 81.4N•m (ARP grease used)

\*Bolt installation torque...Hand tightening (no oil)

#### KAMEARI Reinforced Head Stud Bolt L4 SET

By using stud bolts, the cylinder block threads can be fully used. This distributes the stress generated by tightening over the entire thread, reducing cylinder deformation by about half and improving accuracy. In addition, the use of large-diameter washers increase the contact area, allowing the tightening force to be transmitted over a wide area.



L4 SET ÿ25,500

detail

Outer diameter 22 x Inner diamete 11 x Thickness 3.0 (Reference

outer diameter: ARP = 20) Nut ARP M10 x P1.25
Molybdenum grease ARP No. 100-9908 , wrench size M12 12-Molybdenum grease

used)•Tightening sided 8.3kgf•m (ARP grease torque 81.4N•m (ARP grease used)

\*Bolt installation torque...Hand tightening (no oil)

## L-shaped chromium rocker guide



2.0/2.25/2.50/2.75/3.0/3.25/3.50/3.75 4.0/4.25/4.50/4.75/5.0/5.25/5.5/5.75 6.0/6.25/6.5/6.75/7.0

## L-type oil filler cap



Material: All aluminum

method: Cutting Price: ¥6,500

With DATSUN lettering

method: Casting Price: ¥9,500

(2.0 to 7.0 mm in 0.25 mm increments)

#### L-type DATSUN2400 tappet cover



Nowadays, this is a replica of the premium export tappet cover. It is not only fashionable but also reduces tappet noise.

(Unpainted) ¥72,000

\*Painting costs are not included in the price

#### L-shaped reinforced cam center bolt



Most camshaft knock pin problems are caused by improper tightening of the center bolt. Using a reinforced bolt reduces the load on the

