

# Chrome parts / seats / shift knobs / mirrors / emblems etc.

## Plated parts and stainless steel bolts




- L6 plated tappet cover ¥40,000
- L-shaped plated thermo cover (2 bolts) ¥5,000 (Stainless steel bolts and gasket included)
- L-shaped plated thermo cover (3 bolts) ¥4,500 (Stainless steel bolts and gasket included)
- L6 Plated Water Pump Pulley ¥10,000 (Stainless bolts included)
- L6 plated head front cover ¥3,300 (Stainless steel bolts and gasket included)
- L-shaped plated head triangular cover ¥4,000 (Stainless steel bolts and gasket included)
- L 6 Plated tappet cover bolt ¥3,600
- L4 plated tappet cover bolt ¥2,700
- L-type front cover stainless steel bolt set ¥3,000
- Nissan -type plated hub cap set ¥4,500 (2 pieces set)
- L4 Plated Mechanical Pump Cover ¥5,000 (Stainless steel bolts and gasket included)
- L-shaped plated oil filter cover ¥5,000

\*Only the tappet cover is a standard replacement price.

\*In addition to the L-shaped front cover stainless bolt set, you can add 4 oil pump bolts and 2 thermo housing bolts. Total ¥4,000/1set




## S30 Boots Set (Leather)



Shift lever & side lever boots set 1 set ¥5,000

## S30 Boots Set (Carbon Pattern) Vinyl



Shift lever & side lever boots set Discontinued

## Uni California Classic



Universal door mirror (left and right set) 1 set ¥24,000

(Mirror height x width x length x projection) 92 x 144 x 101 x 148

## Type



Universal fender mirror (left and right set) 1 set ¥20,000

(Mirror diameter x total length x height) 103 x 125 x 110

## Classic Type



Universal fender mirror (left and right set) 1 set ¥24,000

(Mirror diameter x total length x height) 103 x 125 x 110

## GT bucket seat



Production stoppage

KAMEARI bucket seats for historic cars made of high-quality leather. Universal aluminum stays are included, so they can be installed on the genuine seat rails with a little modification.

## S30 genuine seat repair kit



• Early model (up to April 1971) with horizontal stitching. Product number: SE4604, left and right set, ¥75,000

• Early model (S46/May-48) Horizontal stitching Product number: SE4812 Left and right set ¥75,000

• Late model (from January 1974) with vertical stitching. Product number: SE4901, left and right set, ¥75,000

This is a seat reupholstery repair kit made for users who are particular about genuine seats that are no longer manufactured.

## S30 European Grill

Fits: 1969-1978 High quality aluminum construction with powder coated finish Billet aluminum (extruded)

¥40,000



## S30/GC10 emblem



• S30 DATSUN bonnet ¥5,000

• S30 DATSUN Front Fender ¥5,000 • S30 DATSUN Rear Gate ¥3,500

• GC10 GT-kai Front Grille Discontinued

• GC10 GT-modified rear

Production stoppage

## Steering boss



Part number Compatible models

S-021 S30, S130, C130, GC10-R30, 510, 230-430

(Note) GC110 is not compatible

S-022 B110-210 TE series

series (S74.3-), TA series (S77.8-), KP61 S-01 TE27

5,000 (up to S74.3), TA22 series (up to S77.8), KP45-51 S-03 Price :

yen \*Compatible with Momo, Nardi, Personal, etc.

## Wheel cap emblem

• DATSUN-01



• DATSUN-02



• Z-01



Outer diameter x thickness: 48j x

1.0 Material: Water-resistant vinyl coated finish

\*Stick-on type that can be attached by peeling off the backing paper.

• DATSUN-01 ¥2,500 (2-disc set) • DATSUN-02 ¥2,500

(2-disc set) • Z-01 ¥2,500 (2-disc set)